


When a specification, process, or other reference is used with a welding symbol, the reference is put in a *tail bracket* added to the reference line.



Notice that a process always adds the *W* for *welding* or the *B* for *brazing*.


For each symbol and corresponding welding process (below), print the process letter designation in the tail bracket of the welding symbol. (Refer to Table A, page 49.)



Gas Metal Arc Welding




Torch Brazing




Gas Tungsten Arc Welding


Suggestion: Remove page 49 from the packet and place it in front of you so you can refer to Table A as necessary.



GMAW



TB



GTAW