

Usually, the letter designation (abbreviation) for a welding process is made up of the first letter from each word in the process. For example, the abbreviation for Shielded Metal Arc Welding is SMAW.

Print the correct process abbreviation on the line beside each welding process listed below. (Refer to Table A, page 49.)

1. Arc Stud Welding _____

2. Gas Tungsten Arc Welding _____

3. Electrogas Welding _____

4. Flux Cored Arc Welding _____

5. Plasma Arc Welding _____

6. Gas Metal Arc Welding _____

7. Electroslag Welding _____

8. Shielded Metal Arc Welding _____

9. Oxyacetylen Welding _____

10. Submerged Arc Welding _____

1. SW

2. GTAW

3. EGW

4. FCAW

5. PAW

6. GMAW

7. ESW

8. SMAW

9. OAW

10. SAW